

NATIONAL FIREBIRD and TRANS AM CLUB

TECHNICAL SECTIONS Volume II

Reprints from the 1998 thru 2007 NFTAC EAGLE

AVAILABLE ON USB FLASH DRIVE, ON CD, BY EMAIL AND IN PRINTED FORMATS

Volume I covering earlier publications and Volume III covering later publications also available from the NFTAC

PUBLISHED BY THE NFTAC 5433 N. ASHLAND AVE., CHICAGO, IL 60640 U.S.A. phone/text: 773-769-7166



email: info@firebirdtaclub.com
website: firebirdtaclub.com or www.firebirdtransamclub.com

NFTAC TECHNICAL SECTIONS VOLUME II

<u>PUBLICATION</u>	<u>PAGE</u>
1998 February	10
1998 August	15
1998 November	23
1999 February	25
1999 May	30
1999 November	39
2000 February	43
2000 May	49 55
2000 August 2000 November	55 60
2001 Rovernber 2001 February	63
2001 May	67
2001 May 2001 August	70
2001 November	73
2002 February	78
2002 May	83
2002 August	88
2002 November	93
2003 February	97
2003 May	100
2003 August	107
2004 January	114
2004 May	119
2004 August	123
2004 November	130
2005 February	134
2005 May	138
2005 August	142
2006 January	144
2006 May	146
2006 August 2006 November	148 150
2007 February	154
2007 Rebitially 2007 May	154
2007 May 2007 August	160
NFTAC Technical Services	162
NFTAC Store Order Form	163
NFTAC Membership Application	164

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the express written consent of the publisher. The views of contributing writers are their own and not necessarily the views of the NFTAC. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the NFTAC.

ARTICLE INDEX

Publication references in which NFTAC publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q & A), its position on the page and page number in this issue.

SUBJECT/ ARTICLE	ORIGINAL PUBL ISSUE	LICATION PAGE	P A <u>Q & A</u>	AGE NUMBER THIS ISSUE
Brakes				
Adjusting rear discs Brakes shaking steering wheel Drum to disc brakes Parking brake	2002 November 2000 May 2002 November 2002 November	33 35 33 29	3 1 1 1	95 54 95 97
Carburetion/Fuel System				
'72 hood air scoop Aftermarket ram air system Air intake tube Airflow sensor screen Black residue Carb size Cold air induction Fried fuel pump Fuel injector replacement Gasoline vapor smell Gas smell Intake manifold/scoop Ram air intake modification Stalling Stock throttle body Surging TPI Installation Tripower installation Wrong gas	1999 May 2000 August 2004 August 2000 August 2006 August 2005 August 1998 November 2000 August 2001 May 1999 May 1998 November 2006 May 2007 August 2005 May 2001 August 2005 August 2005 August 2001 February 2002 May 2000 November	34 32 32 29 26 22 29 29 32 29 29 22 22 23 32 21 29 29 29	3 1 6 1 1 1 3 1 3 2 2 2 2 1 1 5 4 4 3	35 57 126 56 149 143 24 56 68 33 24 146 160 139 70 142 64 84
Cooling and Heating Systems				
'79 carb fit AC recharging AC removal Cracked heater core Downshift control cable Cooling fans Heater blower Heater core leakage Heater core replacement Heater core removal Low pressure AC port Overheating Overheating Overheats Radiator hose collapse Running hot Running hot with AC on Temperature sending unit	2000 May 2003 August 2001 November 2005 May 2001 November 2005 August 2002 February 2003 February 2000 May 2002 February 2002 February 1999 November 2001 February 1999 November 2004 November 2004 November 2000 November 2004 January 2003 August	29 29 28 23 28 21 32 32 28 28 29 25 32 25 26 29 34 33	2 5 2 3 3 4 4 1 2 1 2 6	50 110 73 139 73 142 80 98 49 78 79 39 65 39 133 60 118 112

SUBJECT/ ARTICLE	ORIGINAL PUBL ISSUE	ICATION PAGE		GE NUMBER THIS ISSUE
Water temperature	2000 August	29	2	56
Windshield defroster	2003 August	29	1	110
Electrical				
'06 & '97 headlight doors	2000 August	33		58
2nd gear start switch	2000 May	28	1	49
32 amp alternator installation	2003 May	32	1	104
4th generation headlight fix	2002 May	33		86
'88 digital dash	2003 May	28	6	102
Another headlight fix	2002 May	34		92
Computer checks	1998 August	29	2	19
ESM reset	2000 February	29		46
Electrical system transfer	1999 May	32	2	34
Firing order	2002 February	32	3	80
Headlight door noise	2002 November	34		96
Headlights	1999 February	34		28
Headlights to stay open	1999 November	25	1	39
Hidden headlight repair	2000 May	33		52
Horn relay	2004 May	33	4	121
Instrument lights	2002 November	28	1	93
Left headlight not opening	2001 August	34	4	72
Low track light	2000 November	32	7	61
Radio codes	2003 May	33	,	105
Radio head unit	2004 August	26	2	123
Radio problem	2004 August 2003 May	27	4	101
Rear lights	2004 January	28	5	115
Service engine light	2004 January 2001 February	28	3	63
SES light	2001 Peditary 2005 May	23	4	139
Stock headlights on 3rd gen	2003 May 2004 January	34	4	118
Turn signal bulb	2004 January 2002 February	28	4	78
Emission Controls				
California smog equipment	1999 February	32	1	26
Fault codes	1999 February 1998 August	29	1	19
Red catalytic converter	2002 February	28	3	78
Engine/Mechanical				
4th generation headlight fix	1999 November	26		40
403 Olds modifications	2007 February	21	1	154
350 & 400 engine difference	2007 Teordary 2002 May	29		84
'67 original engine	2002 May	28	3 5	49
'80 Trans Am with 400	2000 May 2001 February	29	5	64
'81 TA engines	2001 February 2000 August	29	5	56
Belt replacement	1999 February	33	2	27
Belt replacement Belt squealing	2005 February	22	4	134
Bigger engine	2003 February 2001 May	29	3	67
Boring out	2001 May 2002 February	32	1	80
Cadillac engine	2002 February 2007 February	22	2	155
	1999 May	32	1	34
Engine hoist Engine removal	2002 February	32 28	2	78
	2002 February 2002 May	28 34	4	78 92
Engine replacement	2002 May	34		92

V

SUBJECT/ ARTICLE	ORIGINAL PUBL ISSUE	ICATION PAGE	P. <u>Q & A</u>	AGE NUMBER THIS ISSUE
Engine seal replacement	2000 May	32	1	51
Engine setup	1998 February	28	2	10
Engine swap	1999 November	25	7	39
Engine swap Engine swap #2	2001 May	29	4	67
Check engine light	2001 May 2000 August	32	4	57
Check engine light pt. 2	2000 August 2001 May	29	4	67
Horsepower buildup	2001 May 2002 February	32	2	80
Horsepower ratings	2002 February	26	4	43
Idle stall	2000 November	32	1	61
Insulating manifold heat	2004 November	23	2	131
Manifold insulation	1999 February	33	1	27
More horsepower	2000 May	28		49
Motor mounts for 400	2000 May 2002 May	29	3 5	84
Not starting	2002 May	22	2	158
Olds 403 power	2007 May 2001 May	32	3	68
Olds 403 power	2004 August	27	1	124
Olds engine	1999 November	25	5	39
Peak performance	2001 May	32	2	68
Power steering fluid	2001 May 2003 August	27	4	108
Ram air V engine	2000 August	33	4	58
Rattling noise	2000 August 2000 February	27	3	44
RPM surge	2000 February 2001 August	33	2	71
Running rough	2001 August 2001 February	28	1	63
Supercharger	2001 November	32	4	94
Starting problems	2002 November 2001 February	29	1	64
	2001 November	33	1	62
Vortec supercharger Ticking sound	1999 May	33 29	2	33
ricking sound	1999 May	29	2	33
Exhaust				
Aftermarket headers	1999 February	35	1	29
Best Cat-Back exhaust	2002 February	29	3	79
Dual exhaust	2003 February	32	2	98
Edelbrock manifold	2004 January	27	5	114
Edelbrock performer	2001 August	32	4	70
Exhaust manifold bolts	2002 November	32	2	94
Exhaust replacement	2003 August	34		113
Exhaust system replacement	2004 May	28	4	119
Flowmaster	2004 January	33	2	117
Flowmaster exhaust	2002 August	28	3	88
Headers	2002 February	33		81
Headers for a 301	2004 May	28	1	119
Manifolds	2006 August	26	3	149
Muscle car sound	2005 August	21	3 2 2	142
Ram Air III exhaust	2001 February	29	2	64
Exterior/Body				
400 hood	2006 May	22	1	146
'78 Formula t-tops	2000 Way 2000 February	27	1	44
'79 decal set	2000 Peditary 2000 August	32	2	57
'92 model year paint	2000 August 2000 August	29	1	56
American hatch t-tops	2006 November	21	3	150
microan nation t-tops	2000 INOVCINUCI	4 1	3	130

vi

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION ISSUE PAGE		PAGE NUMBER Q&A THIS ISSUE	
Bumper emblem	2000 February	26	1	43
Eagle decal	2005 Hestaary 2005 May	25	1	140
Fiberglass fenders	2005 May	22	1	138
Ground effects	2007 May	22	1	158
GTA emblem	2007 February	26	3	156
Precut striping	2000 May	29	1	50
Rear quarter replacement	2000 November	32	4	61
Rear spoiler replacement	2005 August	22	2	143
Shaker hood scoops	2000 November	29	1	60
Spoilers cracking	2001 May	29	1	67
T-top crack	2002 February	29	4	79
T-top seals	2000 August	28	3	55
Weather-stripping	2002 February	29	1	79
11 0	2002 1 Cordary	2)	1	19
Gauges	2005 F 1	22	1	124
Autometer gauges	2005 February	22	1	134
Gauge Dial repair	1999 November	25	5	39
Generator light	2002 May	32	4	85
General				
14 second car	2001 August	34	1	72
5 Questions	1999 February	29	4	25
'70 1/2 value	2000 February	26	3	43
'78 Redbird	2003 May	26	1	100
'80 pace car	2002 February	32	5	80
'99 Firehawk	2000 November	33	1	62
Acceleration increase	2001 August	34	5	72
Bat out of hell	2001 November	28	1	73
Car storage	1998 February	33		12
Differences in '70 to '73 TAs	1998 August	32		20
F in F-body	2000 August	33		58
First TA production date	2003 May	28	1	102
Make '93 faster	2000 February	26	2	43
NASCAR stickers	2005 February	26	4	136
Performance chips	2000 August	33		58
Performance hints	2002 February	33		81
Performance testing	1999 February	32	2	26
Power steering leak	2002 February	29	2 5	79
Power to '75 Trans Am	2006 August	22	1	148
Power to wheels	2006 January	22	1	144
Research history of car	2005 February	23		135
Restoration	1998 February	28	1	10
Rocket boost	2003 May	33		105
Rollover ratings	2000 February	28		45
Service manual	2002 May	28	2	83
Setting timing	2001 November	29		74
Stated Value Insurance	1998 August	16		15
Trans Am from Firebird	2005 August	21	1	142
Turbo S.E. difference	2002 May	29	1	84
Windshield washer	2002 February	33		81
Winter storage tips	2001 November	29		74

vii

SUBJECT/ ARTICLE	ORIGINAL PUBL ISSUE	ICATION PAGE	PA <u>Q & A</u>	GE NUMBER THIS ISSUE
Windshield washer Y-82 meaning	2002 February 2007 August	34 22	1	82 160
Interior				
Back window removal Bucket seat replacement Console replacement Cracked dash fixing Door alignment Headliner removal Hinges Interior upgrade Loose windows Parchment seat covers Part Changeability Rear deck replacement Seat belt guide removal	2005 May 2002 May 2007 February 2002 November 2004 May 2003 August 2005 February 2002 November 1999 November 2005 May 2001 February 2005 February 2002 May	23 28 29 34 34 33 22 34 25 23 28 26 29	2 1 2 1 2 5 2 2 2 2	139 83 157 96 122 112 134 96 39 139 63 136 84
Seat color Seat covers Steering wheel emblem Steering wheel removal Trunk release Window relay	2006 November 2006 November 2006 November 2002 February 2004 August 1998 November	22 21 26 34 26 28	1 1 1 2	151 150 152 82 123 23
Numbers/Identification Decode 4th generation VIN GM Vin Digit Identification Vin Number Breakdown Vin Number Breakdown pt. 2	1998 February 2000 May 1999 November 2000 February	25 35 28 32		14 54 42 47
Oil/Lubrication The Dirt on oil Oil changes Oil type Posi oil Synthetic oils	1999 May 2004 August 2001 August 2005 August 2006 August	24 26 33 22 26	3 1 3 2	30 123 71 143 149
Suspension/Handling Coil spring replacement Limited slip additive Lowering a 2nd generation Rack and pinion Shocks Spring spacers Suspension improvements Stock Auburn gear Thunking noise Vibration Vibration on 4th generation Vibration problem WS-6 first year	2000 February 1999 May 2004 May 2001 August 2007 February 2006 November 2005 August 2001 August 2001 May 2002 May 2000 November 2002 May 2000 August 	27 29 34 32 26 21 21 32 29 28 33 34 32	2 1 2 1 2 3 3 2 5	44 33 122 70 156 150 142 70 67 83 62 92 57

viii

SUBJECT/ ARTICLE	ORIGINAL PUBL ISSUE	ICATION PAGE	P <u>Q & A</u>	AGE NUMBER THIS ISSUE
WS-6 package	2001 August	32	5	70
WS-7 handling package	2003 August	34	-	113
WS-7 suspension	2002 May	28	3	83
Tires/Wheels				
'70 TA wheel sizes	2002 May	29	7	84
8 inch rims	2003 May	28	5	102
'92 wheels	2001 February	33	1	66
Center caps	2002 November	32	1	94
Long shank lug nuts	1998 November	28	1	23
Restoring wheels	1998 February	35		14
Refinish rims	2002 May	33	2	91
Restoring wheels	004 August	34		128
Tire rotation	2000 May	33		52
Tire replacement	2000 August	28	1	55
Tire size	2004 August	34		128
Tires	1999 February	34		28
Tires pt. 2	2004 November	27		133
Transmission/Clutch/Drive Train				
4.10 rear end	2002 May	32	2	90
700R4 transmission	2000 November	32	5	61
Clunking noise	2000 May	28	5	49
Clutch replacement	2000 November	33	2	62
Gears	2006 May	26	1	147
Hurst usage	2001 August	33	3	71
Powerglide transmission	2007 February	21	2	154
Transmission choice	2002 February	33		81
Transmission leakage	2006 August	22	2	148
Transmission service	2000 May	33		52
Transmission swap	2001 May	33		69
Transmission tuning	1998 August	28	1	18
Transmission tuning pt. 2	2004 August	33	1	127